








1/10





3/10






FIG. 6A




FIG. 6B




FIG. 6C




FIG. 6D




FIG. 7A





FIG. 7

5/10



6/10




FIG. 8A

DETAIL OF THREADS



CONSEQUENCE OF THREADS
 WHICH ARE TOO SOFT
 (RUBBERY) IN COMPRESSION

FIG. 8B

7/10




FIG. 9

8/10




FIG. 10

10/10




FIG. 12
PRIOR ART



Creation date: 09-22-2003
Indexing Officer: EHAILU - ELIZABETH HAILU
Team: OIPEScanning
Dossier: 10661822

Legal Date: 09-02-2003

No.	Doccode	Number of pages
1	TRNA	2
2	SPEC	18
3	CLM	9
4	ABST	1
5	DRW	9

Total number of pages: 39

Remarks:

Order of re-scan issued on